

Scan 85

Aug 2013 >

Door complete
Alu BP 51037836
Alu GP 51047945
Black BP 51045446
Black GP 51047949

Skamol fitting
51046157

Gasket
51045443 AE

Baffleplate
51037831

Baffleplate
51037832

Gasket
51037834 AB

Gasket glass
51044157 AC

Charmotte 51047053

Burn chamber
Charmotte 51037829
Skamol 51046652

Charmotte
51047052

Connection piece
51037779

57850011

Top plate
BP 51046987
GP 51047950

Mantle side left
BP 51047042
GP 51047956

Top incl. top plate
BP 51044160
GP 51047952

Mantle back
BP 51047043
GP 51047957

Upper part ridding grate
51005837

Cast iron bottom
incl. gasket ring
50037778

Gasket ring bottom
51050302

Bauart 1
51037792

Gasket
50037835

Ash drawer
51037783

Handle
BP 51045463
Alu 51045464

Mantle side right
BP 51047041
GP 51047955

Inspection hatch
BP 51050610
GP 51048136

Steel
BP 51037704
GP 51048134
Corner BP 51045292
Corner GP 51048135

Glass
50037707
Corner 50045687

Glass
50043785

Steel
BP 51037705
GP 51048136

Glass
50037708

